


NO. 1510 Cotton bag



Description (measured in cm)	One size
EEE: Height	42
FFF: Width	38
GGG: Depth	12

How to measure



Tolerance +/- in cm

EEE	FFF	GGG
1.5	1.5	1.5

The measurements in a product measurement chart refer to measurements made directly on the clothing. Lay the garment out flat on an even surface without stretching it. Take the measurements as shown by the arrows and select the size that fits. Use a tape measure for the best results. The tolerances in the measurement chart are based on when the item is received from ID® and not