


PRO Wear CARE cardigan | unbrushed | women



Description (research in suc)	VC	C			VI	21/1			EV.	CVI
Description (measured in cm)	XS	S	M	L	XL	2XL	3XL	4XL	5XL	6XL
A: ½ Chest width	47	50	53	57	61	65	69	73	77	81
E: Front length from high point shoulder	63	65	67	69	71	73	75	77	79	81
H: Shoulder to shoulder	38.5	40	41.5	43.5	45.5	47.5	49.5	51.5	53.5	55.5
K: Sleeve length - long	61	62	63	64	65	66	67	67	67	67
L: ½ upper arm width	17.75	18.5	19.25	20	21	22	23	24	25	26

How to measure



Tolerance +/- in cm

А	AEH		к	K2	L	
1.5	1.5	1.5	1.5	1	1	

The measurements in a product measurement chart refer to measurements made directly on the clothing.

Lay the garment out flat on an even surface without stretching it. Take the measurements as shown by the arrows and select the size that fits. Use a tape measure for the best results. The tolerances in the measurement chart are based on when the item is received from ID® and not