


NO. 0310 PRO Wear T-shirt | light



Description (measured in cm)	XS	S	M	L	XL	2XL	3XL	4XL	5XL	6XL
A: ½ Chest width	49	51	53	56	59	63	67	71	75	79
E: Front length from high point shoulder	69	71	73	75	77	79	81	82	83	84
H: Shoulder to shoulder	45	47	49	52	55	59	63	67	71	75
L: ½ upper arm width	22	23	24	25	26	26	27	27	28	28

How to measure



Tolerance +/- in cm

A	E	H	K	K2	L
1.5	1.5	1.5	1.5	1	1

The measurements in a product measurement chart refer to measurements made directly on the clothing. Lay the garment out flat on an even surface without stretching it. Take the measurements as shown by the arrows and select the size that fits. Use a tape measure for the best results. The tolerances in the measurement chart are based on when the item is received from ID® and not