


NO. 0897 Padded jacket | stretch | women



Description (measured in cm)	S	M	L	XL	2XL	3XL
A: ½ Chest width	49	52	55	58	61	64
E: Front length from high point shoulder	62	64	66	68	70	72
H: Shoulder to shoulder	39.5	41	42.5	44	45.5	47
K: Sleeve length - long	64	65	66	67	68	69
L: ½ upper arm width	20	21	22	23	24	25

How to measure



Tolerance +/- in cm

A	E	H	K	L
1.5	1.5	1.5	1.5	1

The measurements in a product measurement chart refer to measurements made directly on the clothing. Lay the garment out flat on an even surface without stretching it. Take the measurements as shown by the arrows and select the size that fits. Use a tape measure for the best results. The tolerances in the measurement chart are based on when the item is received from ID® and not